

PART I: TYPICAL ACCEPTABLE SOLDER CONNECTIONS



FIGURE 13



FIGURE 14




FIGURE 15




FIGURE 16




FIGURE 17




FIGURE 18

PART I. TYPICAL ACCEPTABLE SOLDER CONNECTIONS	
<p>FIGURE 13</p> <p>PWB terminal mounting: Soldering of turret terminal to pad.</p> <p>MINIMUM ACCEPTABLE</p>	<p>FIGURE 14</p> <p>PWB terminal mounting: Soldering of turret terminal to pad.</p> <p>MAXIMUM ACCEPTABLE</p>
<p>FIGURE 15</p> <p>Bifurcated terminal termination: Single wire.</p> <p>MINIMUM ACCEPTABLE</p>	<p>FIGURE 16</p> <p>Bifurcated terminal termination: Single wire.</p> <p>MAXIMUM ACCEPTABLE</p>
<p>FIGURE 17</p> <p>Hook terminal termination; Single wire.</p> <p>MINIMUM ACCEPTABLE</p>	<p>FIGURE 18</p> <p>Hook terminal termination; Single wire.</p> <p>MAXIMUM ACCEPTABLE</p>