


PART I. TYPICAL ACCEPTABLE SOLDER CONNECTIONS	
	
FIGURE 1	FIGURE 2
	
FIGURE 3	FIGURE 4
	
FIGURE 5	FIGURE 6

PART I. TYPICAL ACCEPTABLE SOLDER CONNECTIONS	
<p>FIGURE 1</p> <p>PWB lapped termination; Round lead from same side of PWB to rectangular pad.</p> <p>MINIMUM ACCEPTABLE</p>	<p>FIGURE 2</p> <p>PWB lapped termination; Round lead from same side of PWB to rectangular pad.</p> <p>MAXIMUM ACCEPTABLE</p>
<p>FIGURE 3</p> <p>PWB lapped termination; Round lead through the PWB to rectangular pad.</p> <p>MINIMUM ACCEPTABLE</p>	<p>FIGURE 4</p> <p>PWB lapped termination; Round lead through the PWB to rectangular pad.</p> <p>MAXIMUM ACCEPTABLE</p>
<p>FIGURE 5</p> <p>PWB lapped termination; Ribbon lead from same side of the PWB to rectangular pad.</p> <p>MINIMUM ACCEPTABLE</p>	<p>FIGURE 6</p> <p>PWB lapped termination; Ribbon lead from same side of the PWB to rectangular pad.</p> <p>MAXIMUM ACCEPTABLE</p>