

**PART I. TYPICAL ACCEPTABLE SOLDER CONNECTIONS**



**FIGURE 1**



**FIGURE 2**



**FIGURE 3**



**FIGURE 4**



**FIGURE 5**



**FIGURE 6**

<b>PART I. TYPICAL ACCEPTABLE SOLDER CONNECTIONS</b>	
<p><b>FIGURE 1</b></p> <p>PWB lapped termination; Round lead from same side of PWB to rectangular pad.</p> <p><b>MINIMUM ACCEPTABLE</b></p>	<p><b>FIGURE 2</b></p> <p>PWB lapped termination; Round lead from same side of PWB to rectangular pad.</p> <p><b>MAXIMUM ACCEPTABLE</b></p>
<p><b>FIGURE 3</b></p> <p>PWB lapped termination; Round lead through the PWB to rectangular pad.</p> <p><b>MINIMUM ACCEPTABLE</b></p>	<p><b>FIGURE 4</b></p> <p>PWB lapped termination; Round lead through the PWB to rectangular pad.</p> <p><b>MAXIMUM ACCEPTABLE</b></p>
<p><b>FIGURE 5</b></p> <p>PWB lapped termination; Ribbon lead from same side of the PWB to rectangular pad.</p> <p><b>MINIMUM ACCEPTABLE</b></p>	<p><b>FIGURE 6</b></p> <p>PWB lapped termination; Ribbon lead from same side of the PWB to rectangular pad.</p> <p><b>MAXIMUM ACCEPTABLE</b></p>