


**PART II. TYPICAL UNACCEPTABLE SOLDER CONNECTIONS**



**FIGURE 7**




**FIGURE 8**




**FIGURE 9**



**FIGURE 10**



**FIGURE 11**



**FIGURE 12**

<b>PART II. TYPICAL UNACCEPTABLE SOLDER CONNECTIONS</b>	
<p>FIGURE 7</p> <p>Fractured/disturbed solder connection.</p> <p>UNACCEPTABLE</p>	<p>FIGURE 8</p> <p>Poor wetting.</p> <p>UNACCEPTABLE</p>
<p>FIGURE 9</p> <p>Blowhole</p> <p>UNACCEPTABLE</p>	<p>FIGURE 10</p> <p>Rosin Connection</p> <p>UNACCEPTABLE</p>
<p>FIGURE 11</p> <p>Dewetting.</p> <p>UNACCEPTABLE</p>	<p>FIGURE 12</p> <p>Nonwetting.</p> <p>UNACCEPTABLE</p>

THIS PAGE INTENTIONALLY LEFT BLANK